



MILLINGTON, TN

LITTLE ROCK, AR

## Job Information

Job #: 94509

Date: August 7, 2018

Priority: —

Authorized OT: No

Authorized by:

## Customer Information

Name: Delta Plastics

Motor#:

## Name Plate Information

Manufacturer: Lesson

Enclosure : Totally Enclosed  
Fan Cooled

Horsepower/kW: 15KW

Serial#:

Model#:

Service Factor:

Frame:

Rated RPM:

Rated Voltage:

Phase:

Rated Amps:

Cycles:

Special design: No

## Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: —

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: 6309Z

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6209Z

Retainer condition: —

**WEST TENNESSEE**  
7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

**CENTRAL ARKANSAS**  
6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

## Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	OK
Seals ODE type:	N/A	Bushings/sleeves DE:	Ok
Seals ODE size:		Bushings/sleeves ODE:	Ok
Seals ODE (inbound) condition :			
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	3.9379	Foot flatness:	Pass
Endbell DE insulated?:	—	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	3.3474		
Endbell ODE insulated?:	—		

## Conclusion

Service Tech name: Robert Wiley

Service Tech signature: