

## **Job Information**

Job #:	94517	Date:	August 9, 20
000 ".	0-1017	Date.	/ luguot o

Priority: — Authorized OT: No Authorized by:

## **Customer Information**

Name: Delta Plastics Motor#:

### **Name Plate Information**

Manufacturer: Enclosure: Open Drop Proof Horsepower/kW:

(ODP)

Serial#: Service Factor:

Frame: Rated RPM: Rated Voltage:

Phase: Rated Amps: Cycles:

Special design: No

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Worn Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 22312

Shaft runout(TIR-Inbound): Bearing ODE Size: 22312

Retainer condition: —



## **Mechanical Inspection (Continued)**

Seals DE condition: Worn Brg. Seats DE: Undersized

Seals DE type: Slinger If DE undersized, amt.: 2.3605

Seals DE size: Brg. Seats ODE: Undersized

Seals DE (inbound) condition: If ODE undersized, amt.: 2.3610

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: Foot flatness: **Pass** 

Endbell DE insulated?:

Does Air Gap Meet Customer or EASA spec(<10% variation)? Endbell ODE size:

#### Conclusion

Service Tech name: **Robert Wiley** 

Service Tech signature:

Endbell ODE insulated?:

WEST TENNESSEE CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 7030 Ryburn Drive

Millington, TN 38053 one 901-873-5300 Phone 501-375-9178 Fax 501-375-4254