



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 94526

Date: July 20, 2018

Priority: 1A Rush/OT

Authorized OT: Yes

Authorized by: Day

Customer Information

Name: Steel deal

Motor#:

Name Plate Information

Manufacturer: Lift tech

Enclosure : Totally Enclosed
Non-Ventilated

Horsepower/kW: 4

Serial#: 1323180400

Model#: 1329814-40

Service Factor: 1

Frame: 56z

Rated RPM: 3450

Rated Voltage: 230/460

Phase: 3

Rated Amps: 10.7/9.8/4.9

Cycles: 60

Special design: Yes

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: None

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6204

Retainer condition: Good

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254

Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	OK
Seals ODE type:	Slinger	Bushings/sleeves DE:	Ok
Seals ODE size:		Bushings/sleeves ODE:	Ok
Seals ODE (inbound) condition :			
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:		Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:			
Endbell ODE insulated?:	No		—

Conclusion

Service Tech name: David Williams

Service Tech signature:

