



MILLINGTON, TN

LITTLE ROCK, AR

## Job Information

Job #: 94530

Date: September 5, 2018

Priority: —

Authorized OT: No

Authorized by:

## Customer Information

Name: DeWafelbakkers

Motor#:

## Name Plate Information

Manufacturer:	Taco	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	15
Serial#:	RBH6164039115	Model#:	NPO154	Service Factor:	1.15
Frame:	254T	Rated RPM:	1765	Rated Voltage:	230/460
Phase:	3	Rated Amps:	34.6/17.3	Cycles:	60

Special design: No

## Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: No

Type of grounding device:

Bearing DE Size: 6309 ZZ

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6307 ZZ

Retainer condition: —

**WEST TENNESSEE**  
7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

**CENTRAL ARKANSAS**  
6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

## Mechanical Inspection (Continued)

Seals DE condition : None

Brg. Seats DE: Good

Seals DE type: N/A

If DE undersized, amt.:

Seals DE size:

Brg. Seats ODE: Good

Seals DE (inbound) condition :

If ODE undersized, amt.:

Seals ODE condition : None

Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok

Seals ODE size:

Bushings/sleeves ODE: Ok

Seals ODE (inbound) condition :

Endbell fits/damage: Good

Foot/Flange condition: Ok

Endbell DE size: 3.9373

Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(&lt;10% variation)?

Endbell ODE size: 3.1502

Endbell ODE insulated?: No

—

## Conclusion

Service Tech name: Lynn McDonald

Service Tech signature: