

#### **Job Information**

Job #:	94589				Date:	August 3, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

## **Customer Information**

Name:	A.I.T			Motor#:

# Name Plate Information

Manufacturer:	Lincoln	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:	25
Serial#:	U3970920575	Model#:	TV4593CD2KL14	Service Factor:	1.15
Frame:	284TSC	Rated RPM:	1750	Rated Voltage:	230/460
Phase:	3	Rated Amps:	64/32	Cycles:	60

Special design: No

#### **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6310 2Z/C3
Shaft runout(TIR-Inbound):	.001	Bearing ODE Size:	6310 2Z/C3

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

\_





#### **Mechanical Inspection (Continued)**

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:	Seals ODE size: Bushings/sleeves DE		Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	4.3308	Foot flatness:	Pass
Endbell DE insulated?:	No	Doop Air Con Most Cu	$t_{\rm cm}$ or EASA approx( $z10\%$
Endbell ODE size:	4.3315	variation)?	stomer or EASA spec(<10%
Endbell ODE insulated?:	No	_	

### Conclusion

Service Tech name:

Terrence Holland

Service Tech signature:



Helle

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254