



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 94648

Date: August 24, 2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: Welspun

Motor#:

Name Plate Information

Manufacturer:	Siemens	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	11
Serial#:	N8204824	Model#:	1LAO-163-4YA91Z	Service Factor:	
Frame:	160M	Rated RPM:	1755	Rated Voltage:	460
Phase:	3	Rated Amps:	18	Cycles:	60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Type of grounding device: None

Bearing DE Size: 6209 C3

Shaft runout(TIR-Inbound): .001

Bearing ODE Size: 6209 C3

Retainer condition: Good

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	Other	Shaft damage:	OK
Seals ODE type:	Slinger	Bushings/sleeves DE:	Ok
Seals ODE size:		Bushings/sleeves ODE:	Ok
Seals ODE (inbound) condition :			
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	3.3473	Foot flatness:	Pass
Endbell DE insulated?:	—	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	3.3471		
Endbell ODE insulated?:	No		

Conclusion

Service Tech name: Terrence Holland

Service Tech signature: