

## **Job Information**

Job #: 94650 Date: August 29, 2018

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: Welspun Motor#:

**Name Plate Information** 

Manufacturer: Siemens Enclosure: Totally Enclosed Horsepower/kW: 11

Fan Cooled

Serial#: N8 205104 Model#: 1LAO 163-4YA91- Service Factor:

Z

Frame: 160M Rated RPM: 1755 Rated Voltage: 460

Phase: 3 Rated Amps: 18 Cycles: 60

Special design: No

**Mechanical Inspection** 

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6209 2Z

Shaft runout(TIR-Inbound): .001 Bearing ODE Size: 6209 2Z

Retainer condition: Good



## **Mechanical Inspection (Continued)**

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok Seals ODE size:

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 3.3473 Foot flatness: Pass

Endbell DE insulated?: No

Endbell ODE size:

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

3.3467

## Conclusion

Service Tech name: Terrence Holland

Service Tech signature:

CENTRAL ARKANSAS

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

WEST TENNESSEE

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254