

Job Information

Job #: 94793 Date: October 16,

2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Wright's Cabinets Motor#:

Name Plate Information

Manufacturer: Electro Adda Enclosure: Totally Enclosed Horsepower/kW: 13

Fan Cooled

Serial#: 7061475 Model#: FC132M/2 Service Factor:

Frame: 132M Rated RPM: 3492 Rated Voltage: 230/460

Phase: 3 Rated Amps: 44/22 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: None Bearing DE Size:

Shaft runout(TIR-Inbound): Bearing ODE Size:

Retainer condition: —



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 3.1497 Foot flatness: **Pass**

Endbell DE insulated?: No

> Does Air Gap Meet Customer or EASA spec(<10% Endbell ODE size: 3.1497

variation)?

Endbell ODE insulated?: No

Conclusion

Service Tech name: Terrence Holland

Service Tech signature: