



MILLINGTON, TN

LITTLE ROCK, AR

## Job Information

Job #: 95654

Date: July 25, 2019

Priority: —

Authorized OT: No

Authorized by:

## Customer Information

Name: Kimberly Clark

Motor#:

## Name Plate Information

Manufacturer: Boston Gear Box

Enclosure : Totally Enclosed  
Non-Ventilated

Horsepower/kW:

Serial#:

Model#: RFWA760

Service Factor:

Frame:

Rated RPM: 150:1

Rated Voltage:

Phase:

Rated Amps:

Cycles:

Special design: No

## Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: NA

Shaft runout(TIR-Inbound):

Bearing ODE Size: NA

Retainer condition: —

### WEST TENNESSEE

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

### CENTRAL ARKANSAS

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

## Mechanical Inspection (Continued)

Seals DE condition : Worn

Brg. Seats DE: Good

Seals DE type: Slinger

If DE undersized, amt.:

Seals DE size: NA

Brg. Seats ODE: Good

Seals DE (inbound) condition :

If ODE undersized, amt.:

Seals ODE condition : Worn

Shaft damage: OK

Seals ODE type: Slinger

Seals ODE size: NA

Bushings/sleeves DE: Ok

Bushings/sleeves ODE: Ok

Seals ODE (inbound) condition :

Endbell fits/damage: Good

Foot/Flange condition: Ok

Endbell DE size: NA

Foot flatness: Pass

Endbell DE insulated?: No

Endbell ODE size: NA

Does Air Gap Meet Customer or EASA spec(&lt;10% variation)?

Endbell ODE insulated?: No

—

## Conclusion

Service Tech name: Robert Wiley

Service Tech signature: