



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Job Information

Job #: 140398

Date: August 13, 2019

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: Lemm corp.

Reason:

Contact:

Motor#:

PO#:

Application: —

Special notes:

Name Plate Information

Manufacturer: RENOLD INC.

Enclosure : Open Drop Proof (ODP)

Horsepower/kW: 1.88

Serial#: R/KBC3-400-6

Rated Voltage: 460

Phase:

Rated RPM: 1128

Service Factor:

Special design: No

Cycles:

Rated Amps: 2.3

Model#:

Frame:

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Mechanical Inspection

Shaft grounding device present?:	No	Shaft runout(TIR-Inbound):	.0005
Bearings Retainer:	Yes	Retainer condition:	—
Bearing Type:	Cylindrical roller	IS BEARING A THRUST BRG:	NO
DE BEARING NAME AND NUMBER:	FAG NJ2309	ODE BEARING NAME AND #:	FAG NJ 2309
DE BEARING SIZE I.D.:		ODE BEARING SIZE I.D.:	
DE BEARING SIZE O.D.:		ODE BEARING SIZE O.D.:	
Is bearing Insulated:	No	Is bearing Insulated:	No
Thermal Protection:	No	Thermal Protection Type:	—



WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Mechanical Inspection (Continued)

DE SHAFT
IMAGE:



ODE SHAFT IMAGE:



Water jacket: N/A

Fan: N/A

Frame cond.: Good



Motor Mount
Position: Horizontal/Foot mount

Endbell type: Single piece

DE Endbell Image:



ODE Endbell Image:



WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Mechanical Inspection (cont)

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

DE AND ODE SEAL TYPE: Other

DE SHAFT EXT.: 1.575

ODE SHAFT EXT.: 1.575

DE SHAFT EXT. KEYWAY: .316

ODE SHAFT EXT. KEYWAY: .316

DE SHAFT AIR SEAL (inner):

ODE SHAFT AIR SEAL (inner):

(Outer): 1.770

(Outer): 1.770

DE SHAFT BRG JOURNAL : 1.7726

ODE SHAFT BRG JOURNAL : 1.77226

If journal is undersize,amount:

If journal is undersize,amount:

DE BEARING SEAT: Good

ODE BEARING SEAT: Good

Shaft damage cause: None

REPAIR OR REPLACE SHAFT:

ANY OTHER SHAFT DAMAGE NOT
PREVIOUSLY MENTIONED:

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Mechanical Inspection (Continued)

DE Endbell fits/damage: Good

ODE Endbell fits/damage: Good

DE END BELL BRG FIT: 3.937

ODE END BELL BRG FIT: 3.937

DE END BELL AIR SEAL: 1.807

ODE END BELL AIR SEAL: 1.807

Endbell DE insulated?: No

Endbell ODE insulated?: No

Bushings/sleeves DE: Ok

Bushings/sleeves ODE: Ok

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Yes

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Conclusion

LIST MACHINE WORK
REQUIRED : NO MACHINE WORK REQ'D

Service Tech name: BILLY MAYS

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254