



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Job Information

Job #:

140611

Date:

September 19,
2019

Priority:

—

Authorized OT:

No

Authorized by:

Customer Information

Name:

Big river steel

Reason:

Contact:

Motor#:

PO#:

Application:

—

Special notes:

Name Plate Information

Manufacturer:

Enclosure :

Open Drop Proof
(ODP)

Horsepower/kW:

Serial#:

Rated Voltage:

Phase:

Rated RPM:

Service Factor:

Special design:

No

Cycles:

Rated Amps:

Frame:

Model#:

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254

Mechanical Inspection

Shaft grounding device present?: No

Shaft runout(TIR-Inbound): .000

Bearings Retainer: No

Retainer condition: —

Bearing Type: Ball

IS BEARING A THRUST BRG: NO

DE BEARING NAME AND NUMBER: NSK 6306

ODE BEARING NAME AND #: NSK6306

DE BEARING SIZE I.D.: 30MM

ODE BEARING SIZE I.D.: 30MM

DE BEARING SIZE O.D.: 72MM


ODE BEARING SIZE O.D.: 72MM

Is bearing Insulated: No

Is bearing Insulated: No

Thermal Protection: Yes

Thermal Protection Type: —





MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Mechanical Inspection (Continued)

DE SHAFT
IMAGE:



ODE SHAFT IMAGE:



Water jacket:

N/A

Fan:

Ok

Frame cond.:

Good

Motor Mount
Position:

Horizontal/Flange mount

Endbell type:

Single piece

DE Endbell Image:



ODE Endbell Image:



WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Mechanical Inspection (cont)

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:

Good

DE AND ODE SEAL TYPE:

Other

DE SHAFT EXT.:

1.1278

ODE SHAFT EXT.:

.3934

DE SHAFT EXT. KEYWAY:

.309

ODE SHAFT EXT. KEYWAY:

N/A

DE SHAFT AIR SEAL (inner):

N/A

ODE SHAFT AIR SEAL (inner):

N/A

(Outer):

1.184

(Outer):

1.184

DE SHAFT BRG JOURNAL :

1.1815

ODE SHAFT BRG JOURNAL :

1.1815

If journal is undersize,amount:

.000

If journal is undersize,amount:

.000

DE BEARING SEAT:

Good

ODE BEARING SEAT:

Good

Shaft damage cause:

None

REPAIR OR REPLACE SHAFT:

ANY OTHER SHAFT DAMAGE NOT
PREVIOUSLY MENTIONED:

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Mechanical Inspection (Continued)

DE Endbell fits/damage:

ODE Endbell fits/damage:

DE END BELL BRG FIT:

ODE END BELL BRG FIT:

DE END BELL AIR SEAL:

ODE END BELL AIR SEAL:

Endbell DE insulated?:

Endbell ODE insulated?:

Bushings/sleeves DE:

Bushings/sleeves ODE:

Does Air Gap Meet Customer or EASA spec(<10% variation)?

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

MECHANICAL EVALUATION

Conclusion

LIST MACHINE WORK
REQUIRED :

NONE REQ'D

Service Tech name:

BMAYS

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254