



MILLINGTON, TN

LITTLE ROCK, AR

## Job Information

Job #: 138286

Date: October 10, 2018

Priority: —

Authorized OT: No

Authorized by:

## Customer Information

Name: PLASKOLITE, inc.

Motor#:

## Name Plate Information

Manufacturer: BALDOR

Enclosure : Totally Enclosed  
Fan Cooled

Horsepower/kW: .43

Serial#: N/A

Model#: N/A

Service Factor: N/A

Frame: 56YZ

Rated RPM: 1760

Rated Voltage: 230/460

Phase: 3

Rated Amps: 2.2/1.1

Cycles: 60

Special design: No

## Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: 6205

Shaft runout(TIR-Inbound): .001

Bearing ODE Size: 6203

Retainer condition: Good

### WEST TENNESSEE

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

### CENTRAL ARKANSAS

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

## Mechanical Inspection (Continued)

DE shaft extension :	.375	Shaft damage:	OK
DE shaft extension keyway:	.125	Shaft Brg. Journal DE:	Good
ODE shaft extension :	N/A	If DE undersized, amt.:	
ODE shaft extension keyway:	N/A		
Shaft air Seal DE size:	.984	Shaft Brg. Journal ODE:	Good
Shaft air Seal ODE size:	.669	If ODE undersized, amt.:	
DE Endbell fits/damage:	Good	ODE Endbell fits/damage:	Good
Endbell DE size:	2.0479	Endbell ODE size:	1.5753
Endbell DE air seal size:	.995	Endbell ODE air seal size:	.680
Endbell DE insulated?:	No	Endbell ODE insulated?:	No
		Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Foot flatness:	Pass	Yes	

## Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

**WEST TENNESSEE**  
7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

**CENTRAL ARKANSAS**  
6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254