



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 138560

Date: November 30,
2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: SANDUSKY METAL CABINET

Motor#:

Name Plate Information

Manufacturer:	RELIANCE	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	100
Serial#:	02MAN58308	Model#:	N/A	Service Factor:	1.15
Frame:	365TSD	Rated RPM:	3550	Rated Voltage:	460
Phase:	3	Rated Amps:	111	Cycles:	60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Damaged

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: 6313

Shaft runout(TIR-Inbound): .002

Bearing ODE Size: 6313

Retainer condition: Good

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

DE shaft extension :	1.8745	Shaft damage:	Salvageable
DE shaft extension keyway:	.5	Shaft Brg. Journal DE:	Good
ODE shaft extension :	N/A	If DE undersized, amt.:	.000
ODE shaft extension keyway:	N/A	Shaft Brg. Journal ODE:	Undersized
Shaft air Seal DE size:	2.559	If ODE undersized, amt.:	-.0042
Shaft air Seal ODE size:	2.555	ODE Endbell fits/damage:	Bad
DE Endbell fits/damage:	Good	Endbell ODE size:	5.515
Endbell DE size:	5.5118	Endbell ODE air seal size:	2.625
Endbell DE air seal size:	2.580	Endbell ODE insulated?:	No
Endbell DE insulated?:	No	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Foot flatness:	Pass	Yes	

Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254