



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 138888

Date: January 14, 2019

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: GE AVIATION

Motor#:

Name Plate Information

Manufacturer:	GE	Enclosure :	Totally Enclosed Air Over (TEAO)	Horsepower/kW:	25
Serial#:	CTH6083514002	Model#:	5KE284AC205C	Service Factor:	N/A
Frame:	284T	Rated RPM:	1760	Rated Voltage:	230/460
Phase:	3	Rated Amps:	60/30	Cycles:	60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Damaged

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: 6312

Shaft runout(TIR-Inbound): .001

Bearing ODE Size: 6310

Retainer condition: —

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

DE shaft extension :	1.374	Shaft damage:	Salvageable
DE shaft extension keyway:	.500	Shaft Brg. Journal DE:	Undersized
ODE shaft extension :	N/A	If DE undersized, amt.:	.0015
ODE shaft extension keyway:	N/A	Shaft Brg. Journal ODE:	Good
Shaft air Seal DE size:	1.363	If ODE undersized, amt.:	.000
Shaft air Seal ODE size:	N/A	ODE Endbell fits/damage:	Good
DE Endbell fits/damage:	Good	Endbell ODE size:	4.331
Endbell DE size:	5.119	Endbell ODE air seal size:	N/A
Endbell DE air seal size:	2.176	Endbell ODE insulated?:	No
Endbell DE insulated?:	No	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Foot flatness:	Pass	Yes	

Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254