

**AC Recondition Repair Report** 

FolderID: 97720 FormID: 9743225

7030 Ryburn Dr Millington, Tn 38053 901-873-5300

Hi-Speed Industrial Service

Welspun Tubular (11685)

9301 Frazier Pike Little Rock, AR 72206

Priorities Found: 1 - High

13 - Good

Genera	General			
1.	Job Number	97720		
2.	Report Date			
3.	Customer	Welspun		
Name	Name Plate Information			

Rodgau P5 Manufacturer


































5.	Model	FOM160L-4
6.	Serial Number	06062662
7.	Horsepower	18 HP
8.	KW	
9.	Volts	480 Volts
10.	Amps	16.5 Amps
11.	RPM	1752 RPM
12.	Frame	160L
13.	Enclosure	TEFC
14.	Cycles	60 HZ
15.	Phase	3 PH



17. Motor Mount Position

## **Initial Inspection**

0

18. Number of Leads P13



- 19. Lead Length
- 20. Lead Size
- 21. Lead Condition
- 22. Lead Markings
- 23. Lug Size, Condition, and Type
- 24. Winding RTD's
- 25. Winding Rtd's Condition
  - 26. Shaft Run Out
  - 27. Does Shaft Turn Freely
  - 28. Does Shaft Have Visible Damage

no

P94



- 29. Bearing Rtd's
- 30. Bearing Rtd's Condition
- 31. Contamination

32. Frame Condition

(P) Pass

P106



P109 33. Fan Condition



## 34. Broken or missing components **Initial Electric Test** 0 35. Resistance to Ground 36. Winding Resistance 1-2 37. Winding Resistance 2-3 38. Winding Resistance 1-3 39. Resistive Imbalance 40. Hi-Pot









42. Stator Condition good P65



43. Failure Location

**Initial Rotor Inspection** 

0





45.	Air Gap <10% Variation		
46.	Number of Rotor Bars		
47.	Number of Broken Rotor Bars	0	
48.	Growler Test	(P) Pass	
49.	Rotor Condition	(P) Pass	P50



## Mechanical Inspection 50. Bearing Manufacture

0

nsk

P1





51.	Bearing DE Size	6309	
52.	Bearing DE Type	ball bearing	
53.	DE Bearing Qty.	1	



55. Bearing ODE Type ball bearing P53





56.	ODE Bearing Qty.	1	
57.	Insulated Bearing		
58.	Lubrication Type	grease	
59.	Grease Condition	(F) Fail	
60.	Bearing Retainers	(Y) Yes	P80



61.	Shaft Grounding Device	(NA) Not Applicable	
62.	DE Seal	(Y) Yes	
63.	DE Seal Type/Size	45*62*12	P90



64. ODE Seal

(Y) Yes



65. ODE Seal Type/Size

Root C	Root Cause of Failure	
66.	Component Failure	bearings
67.	Cause of Failure	
	Worn/dirty/contaminated grease	
68.	Comments	
	Recondition motor.	
69.	Service Technician	Terrence Holland

Jonne Holland

Mac	Machine Fit Inspection Report		
• 7	70.	Shaft Run Out	(P) Pass
7	71.	Initial Shaft Run Out	0.002 "
7	72.	Final Shaft Run Out	
• 7	73.	DE Bearing Shaft Fit	(P) Pass
7	74.	DE Initial Shaft Bearing Fit Size 1	1.772 "
7	75.	DE Initial Shaft Bearing Fit Size 2	1.772 "
7	76.	DE Initial Shaft Bearing Fit Size 3	1.772 "
7	77.	DE Finial Shaft Bearing Fit Size 1	
7	78.	DE Finial Shaft Bearing Fit Size 2	
7	79.	DE Finial Shaft Bearing Fit Size 3	
• 8	30.	ODE Bearing Shaft Fit	(P) Pass
8	31.	ODE Initial Shaft Bearing Fit Size 1	1.7718 "
8	32.	ODE Initial Shaft Bearing Fit Size 2	1.7717 "
8	33.	ODE Initial Shaft Bearing Fit Size 3	1.7716 "
8	34.	ODE Finial Shaft Bearing Fit Size 1	
8	35.	ODE Finial Shaft Bearing Fit Size 2	
8	36.	ODE Finial Shaft Bearing Fit Size 3	
8	37.	DE Air Seal Shaft Fit	
8	38.	DE Initial Air Seal Shaft Size	
8	39.	DE Final Air Seal Shaft Size	
9	90.	ODE Air Seal Shaft Fit	

	91.	ODE Initial Air Seal Shaft Size		
	92.	ODE Final Air Seal Shaft Size		
	93.	DE Endbell Fit	(P) Pass	
	94.	DE Initial Endbell Fit Size 1	3.9368 "	
	95.	DE Initial Endbell Fit Size 2	3.937 "	
	96.	DE Initial Endbell Fit Size 3	3.9372 "	
	97.	DE Final Endbell Fit Size 1		
	98.	DE Finial Endbell Fit Size 2		
	99.	DE Final Endbell Fit Size 3		
	100.	DE Endbell Fit Insulated		
	101.	DE Endbell Air Seal Fit		
	102.	Initial Endbell Air Seal Fit Size		
	103.	Finial Endbell Air Seal Fit Size		
	104.	ODE Endbell Fit	(P) Pass	
	105.	ODE Initial Endbell Fit Size 1	3.9372 "	
	106.	ODE Initial Endbell Fit Size 2	3.9371 "	
	107.	ODE Initial Endbell Fit Size 3	3.9372 "	
	108.	ODE Final Endbell Fit Size 1		
	109.	ODE Final Endbell Fit Size 2		
	110.	ODE Final Endbell Fit Size 3		
	111.	ODE Endbell Fit Insulated		
	112.	ODE Endbell Air Seal Fit		
	113.	ODE Initial Endbell Seal Fit Size		
	114.	ODE Finial Endbell Seal Fit Size		
	115.	Foot Flatness	(NA) Not Applicable	
	116.	Foot Condition	(NA) Not Applicable	
	117.	Flange Condition	(P) Pass	P158



118. Service Technician

**Terrence Holland** 

## **Balancing Report**

119. Balance Type

400	
	Balance Operating Speed
	Start Left End
	Start Right End
123.	Balancing Specification
124.	Finish Left End
125.	Finish Right End
126.	Service Technician
Assem	bly and Final Test
127.	Meggar Testing Reading
128.	Surge Test
129.	Hi-Pot
130.	Winding Resistance 1-2
131.	Winding Resistance 2-3
132.	Winding Resistance 1-3
133.	Test Run Voltage Phase A
134.	Test Run Amps A
135.	Test Run Voltage Phase B
136.	Test Run Amps B
137.	Test Run Voltage Phase C
138.	Test Run Amps C
139.	DE Horizontal Vibration Reading
140.	DE Vertical Vibration Reading
141.	DE Axial Vibration Reading
142.	ODE Horizontal Vibration Reading
143.	ODE Vertical Vibration Reading
144.	ODE Axial Vibration Reading
145.	Ambient Temp at start of Test Run
146.	Temp at 5 minutes
147.	Temp at 10 minutes
148.	Temp at 15 minutes
149.	Temp at 20 minutes
150.	Temp at 25 minutes
151.	Temp at 30 minutes
152.	Temp at 35 minutes
153.	Temp at 40 minutes
154.	Temp at 45 minutes
155.	Temp at 50 minutes
156.	Temp at 55 minutes
157.	Temp at 60 minutes
158.	
159.	Service Technician

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.