





Asset # 1226

The infrared data indicates a high resistance connection that is 50* higher than the other connections . Clean and tighten connection.

4/12/2021 6:46:13 AM



4/12/2021 6:46:23 AM



Measurements

Sp1	148.8 °F
Sp2	98.7 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F