




Asset #2609


Infrared data indicates a high resistance connection on phase A. Clean terminal and wire. inspect for damage and replace as necessary.

4/12/2021 7:12:07 AM



IR_1781.jpg S60 NTSC 21801575

4/12/2021 7:12:14 AM



DC_1782.jpg

Measurements

Sp1	106.9 °F
Sp2	161.0 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F