





Asset #2652

Infrared data indicates a high resistance connection on the load side of phase C. Clean terminal and wire, inspect for damage. Replace as needed.

4/12/2021 7:15:25 AM



4/12/2021 7:15:34 AM



Measurements

Sp1	94.9 °F
Sp2	108.0 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F