


8/11/2021 7:29:36 AM



8/11/2021 7:29:47 AM



Measurements

Bx1	Max	143.4 °F
	Min	94.5 °F
	Average	105.6 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates a high resistance connection on the load side of A phase of control relay 3030. Check for damage replace if necessary ,clean wire and tighten to proper torque.