



8/11/2021 7:39:08 AM



8/11/2021 7:39:18 AM



Measurements

Sp1	140.4 °F
Sp2	138.4 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicate a high resistance connection on the line and load side of phase C . Check the contacts for damage. Replace if necessary and inspect the wire for damage, and repair as necessary tighten to proper torque.