

## **Job Information**

Job #	: 95949				Date	: April 9, 2020	
Priority	: –	Authorized OT:	No	Auth	norized by	:	
Custom	er Information						
Name:	Morrilton Packing				Motor#	:	
Name P	late Informatio	n					
Manufacturer: BAUMULLER		R Enclo			Open Drop Proof (ODP)		
Serial#: 10300678		М	Model#: GN				
Service Factor:		F	rame:				
Horsepower	/kW: 135KW	Rated	RPM:				
Armature	Volts 400		Fields	Volts	310		
	Amps 365		-		6.5		
Test Ru	n Inspection	this motor and ve	erified th	nat all elec	Date trical tes	April 9, 2020 Its are complete	
	-						
Power Su	pply						
	Р	hase A	Phase	θB	Pha	se C	
No Load Voltage 400		400	230				
No Load Current 7.8		7.8	6.5				

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



## **Test Run Inspection (Continued)**

**Temperatures: (Degrees Fahrenheit)** 

Test run ball-bearing motors for 15 minutes. Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

# **Ambient Temp:** TIME DE Degree Change ODE **Degree Change** START: 5 MIN: 10 MIN: 15 MIN: 20 MIN: 25 MIN: 30 MIN: 35 MIN: 40 MIN: 45 MIN: 50 MIN: 55 MIN:

#### 60 MIN:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



## **Test Run Inspection (Continued)**

Peak (Readings sho	(Readings should be less than .08 In/Sec Peak)						
Horizontal	VDE	Axial					
Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)							
Magnetic Center line distance from shaft shoulder							
Magnetic Center line distance from all the way out mark							
Magnetic Center line distance from all the way in mark							
	Horizontal Irements (Only App ance from shaft should ance from all the way o	Horizontal VDE rements (Only Applies to Sleeve Bearing ance from shaft shoulder ance from all the way out mark					

Total Motor End Float

### **Additional photos**









Yes, the shaft has been isolated for delivery.

Service Tech name:

Robert Wiley

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254