

Job Information

Job #: 137836 Date: August 1, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Toyota boshoku tenn Motor#:

Name Plate Information

Manufacturer: Yaskawa Enclosure: Open Drop Proof

(ODP)

Serial#: 514e77101 Model#:

Service Factor: Frame:

Horsepower/kW: 75 kw Rated RPM: 1750

Armature Volts 440 Fields Amps 187 Amps

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6312

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6316

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: RTD



Mechanical Inspection (Continued)

Seals DE type: Slinger Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound)

condition:

Seals ODE condition: Worn

Seals Image 2:

Seals ODE type: Slinger Not

Seals ODE size:

Available

Seals ODE (inbound)

condition:

Lubrication Type: Oil Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand

outbound:

Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE condition: Worn



Mechanical Inspection (Continued)

Brg. Seats DE: Good Shaft damage: OK

If DE undersized, amt.: .000 Shaft damage cause: None

Brg. Seats ODE: Good Bushings/sleeves DE: Ok

If ODE undersized, amt.: .000 Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Endbell type: Single piece

Endbell DE size: 5.119 Endbell ODE size: 6.6934

Endbell DE insulated?: No Endbell ODE insulated?: No

Conclusion

Service Tech name: Billy mays

Service Tech signature: