



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 139383

Date: April 15, 2019

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: CHEM-TAINER IND. INC

Motor#:

Name Plate Information

Manufacturer: DEMER

Enclosure : Open Drop Proof
(ODP)

Serial#: OD785

Model#: QCCAS71L

Service Factor:

Frame:

Horsepower/kW:

Rated RPM:

Armature

Volts 150

Amps 7.9

Fields

Volts 200

Amps 0.36

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Bearings DE: Worn

Bearings DE make: NTN

Insulated: No

Bearing DE Size: 6204

Bearings ODE: Worn

Bearings ODE make: NTN

Bearing Type: Ball

Bearing ODE Size: 6201

Bearings Retainer: Yes

Thermal Protection: Yes

Retainer condition: —

Thermal Protection Type: —

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE type: Slinger

Seals DE size:

Seals DE (inbound)
condition :

Seals ODE condition : Worn

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound)
condition :

Lubrication Type: Oil

Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM

Thermal Protection device ODE: —

Lubrication brand
outbound: Mobile Polyrex EM

Grease Amt DE: Full

Grease Cond. DE: New

Grease Amt ODE: Full

Grease Cond. ODE: New

Seals DE condition : Worn

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

Brg. Journal DE: Good

Shaft damage: Salvageable

If DE undersized, amt.:

Shaft damage cause: Other

Brg. Journal ODE: Good

Bushings/sleeves DE: Other

If ODE undersized, amt.:

Bushings/sleeves ODE: Ok

Endbell type: Single piece

DE Endbell fits/damage: Good

ODE Endbell fits/damage: Good

Endbell DE size: 1.851

Endbell ODE size: 1.260

Endbell DE airseal: .785

Endbell ODE airseal: .473

Endbell DE insulated?: No

Endbell ODE insulated?: No

Conclusion

MACHINE WORK
REQ'D:

REPAIR SLIGHT DING TO EXT.SHAFT D. E.KEY WAY

BORE NEW FAN

TURN AND UNDERCUT COMMUTATOR

Service Tech name: BILLY MAYS

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254