

### **Job Information**

Job #: 139436 Date: March 28, 2019

Priority: — Authorized OT: No Authorized by:

#### **Customer Information**

Name: Toyota BOSHOKU tenn Motor#:

#### **Name Plate Information**

Manufacturer: YASKAWA Enclosure: Open Drop Proof

(ODP)

Serial#: Model#:

Service Factor: Frame: 280BD

Horsepower/kW: 185KW Rated RPM: 1750

Armature Volts 440 Volts 150

Amps 451 Amps 12.7

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: NU22

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6316

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: —



### **Mechanical Inspection (Continued)**

Seals DE type: Slinger Seals Image:

Seals DE size: 3.630

Seals DE (inbound)

condition :

Seals ODE condition: Worn

Seals ODE type: Slinger

Seals ODE size: 4.900

Seals ODE (inbound) 4.900

condition:

als Image:

Seals Image 2:



Lubrication Type: Oil Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: -

Lubrication brand

outbound:

Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE condition: Worn

Fax 901-873-5301



## **Mechanical Inspection (Continued)**

Brg. Seats DE: Good Shaft damage: OK

If DE undersized, amt.: NONE Shaft damage cause: None

Brg. Seats ODE: Good Bushings/sleeves DE: Ok

If ODE undersized, amt.: NONE Bushings/sleeves ODE: Ok

Endbell fits/damage: Bad Endbell type: Single piece

Endbell DE size: 9.448 Endbell ODE size: 6.695

Endbell DE insulated?: No Endbell ODE insulated?: No

### Conclusion

Service Tech name: BILLY MAYS

Service Tech signature: