

Job Information

Job #:	94826			Date:	October 18, 2018
Priority:	_	Authorized OT:	No	Authorized by:	
Custome	er Information				
Name:	Flakeboard			Motor#:	
Name Pla	ate Information				
Manufactu	rer: Reliance	Enclosu	ire :	Totally Enclosed Non-Ventilated	
Serial#:		Mod	el#:	6632576	
Service Factor: 1.0		Fra	me:	MC3612ATZ	
Horsepower/kW: 100		Rated R	PM:	1750	
Г				Valta 200	_
Armature	Volts 500	Fie	Fields	Volts 300	
L	Amps 160			Amps 3.93	_

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	6219 2Z
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6216 2Z
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	Good	Thermal Protection Type:	_

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE type:	N/A	Seals Image:	
Seals DE size:			Not Available
Seals DE (inbound) condition :			
Seals ODE condition :	None	Seals Image 2:	
Seals ODE type:	N/A		Not
Seals ODE size:			Available
Seals ODE (inbound) condition :			
Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	Gritty
Grease Amt ODE:	Full	Grease Cond. ODE:	Gritty
Seals DE condition :	None		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Brg. Seats DE:	Good	Shaft damage:	ОК
If DE undersized, amt.:		Shaft damage cause:	None
Brg. Seats ODE:	Good	Bushings/sleeves DE:	Ok
If ODE undersized, amt.:		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Endbell type:	Single piece
Endbell DE size:	6.6939	Endbell ODE size:	5.5128
Endbell DE insulated?:	No	Endbell ODE insulated?:	No

Conclusion

Service Tech name:

Terrence Holland

Service Tech signature:

Holle

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254