

## Job Information

Job #: 96288

Date: December 10, 2019

Priority: —

Authorized OT: No

Authorized by:

## Customer Information

Name: Kobe

Reason:

Contact:

Motor#:

PO#:

Application: —

Special notes:

## Name Plate Information

Manufacturer: Westinghouse

Enclosure : Open Drop Proof (ODP)

Enclosure Type image

Serial#: 17S7B9400

Model#:

Service Factor:

Frame: 63-A

Horsepower/kW: 15

Rated RPM: 750/850



Armature

Volts 230

Amps 60

Fields

Volts 125

Amps 0

Nameplate

DE

ODE

F1

F2

Top



## Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No

Contaminant(s): None

Shaft rotation: Bi-directional

Contaminant(s) Amt: None

Shaft Condition: Good

Contaminant Image:

Shaft grounding device present?: No

Not Available

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Oil

Thermal Protection device DE: N/A

Lubrication brand inbound: Unknown

Thermal Protection device ODE: N/A

Lubrication brand outbound: Unknown

Grease Amt DE: 0

Grease Cond. DE: Other

Grease Amt ODE: 1/4

Grease Cond. ODE: Other

### WEST TENNESSEE

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

### CENTRAL ARKANSAS

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254

## Mechanical Inspection (Continued)

Brushholders

- Number 8
- Condition Good
- Size
- Spring type

Brushes

- Number 8
- Size
- Shunt Len.
- Insulated No
- TermType


Brg Image



Shaft Image



Brushing/sleeves



End bell



Water jacket: N/A

Fan: N/A

Frame cond.: Good

Not  
Available

Not  
Available



Motor Mount Position: Horizontal/Foot mount

Foot/Flange condition: Ok

Foot flatness: Pass



MILLINGTON, TN

LITTLE ROCK, AR

## Mechanical Inspection (Continued)

Missing parts?

☒ J-Box cover    ☐ O-rings    ☐ J-Box    ☐ HH cover    ☐ Glands    ☐ None

Other missing parts

### Air Gap Measurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0	ODE @ 0	—
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

## Electrical Inspection

☐ Move armature imbalance to Assemble    Commutator:    Salvageable

## Winding Inspection

Meg Test IP to Flds:    Good    Polarity Check IP to Flds:    Yes

Meg Series to Shunt:    Good

**WEST TENNESSEE**  
7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301


**CENTRAL ARKANSAS**  
6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254



## DC Electrical Inspection

Brushes: Normal wear

Brush Image:




Brush holders: Salvageable Qty. 8

Insulators: Salvageable Qty. 4

Lead support stud: Salvageable Qty. 6

Alternate brush image:



Rocker ring: Salvageable Qty. 0

Commutator Type: Tig welded

Commutator images

Commutator Hardness: Good

Commutator Condition : Oil soaked

Commutator Film: Ok



Armature type: Factory If other

Armature images

Failure mode: Ok If other

Failure location: Other If other

Armature condition: Solid If other



Winding color: Like new

## DC Electrical Inspection (Continued)

### Armature Test Results

Armature image



Megs: Good Hi-pot: Good Core loss: Good

### Fields condition

Series/Stab condition: Other

Fields condition image:



Shunts condition: Shorted turn-turn

InterCoils condition: Ok

### Fields test results

Series/Stab Meg: Ok Hi Pot: Ok Resistance: Ok

Shunts Meg: Ok Hi Pot: Bad Resistance: Bad

InterCoils Meg: Ok Hi Pot: Ok Resistance: Ok

Thermistors: None

Field Test image

RTD: None At

Thermostat: None

Not Available



MILLINGTON, TN

LITTLE ROCK, AR

Leads/jumpers: Ok

Lead jumper Image:

Not  
Available

## Conclusion

Component Failure

Cause of Failure

## Comments

New brushes Field rewind reload inter poles resleeve ODE End Bell

Service Tech name: Robert Wiley

Service Tech  
signature:

### WEST TENNESSEE

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

### CENTRAL ARKANSAS

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254